

Page 1/8

## Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023

Version number 23 (replaces version 22)

Revision: 12.08.2023

## SECTION 1: Identification of the substance/mixture and of the company/ undertaking

· Trade name	
r Trade name	<u>MC-RIM PROTECT</u>
• Article number: • 1.2 Relevant identified uses of the substance or mixture	3020
and uses advised against • Application of the substance	No further relevant information available.
/ the mixture	Mineral coating
· 1.3 Details of the supplier of the	he safety data sheet
Manufacturer/Supplier:	MC-Bauchemie Müller GmbH & Co. KG
	Am Kruppwald 1-8
	D-46238 Bottrop
	Tel.: +49(0)2041-101-0
	Fax.: +49(0)2041-101-400
	E-Mail: info@mc-bauchemie.de
	MC-Bauchemie AG
	Hagackerstr. 10
	CH-8953 Dietikon
	Tel.: +44-7400510
	Fax : +44-7400533
<ul> <li>Informing department:</li> <li>1.4 Emergency telephone</li> </ul>	msds@mc-bauchemie.de
number:	Tel.: +49 / (0)700 24112112 (MCR)
	Tel.: +48612864565

### **SECTION 2: Hazards identification**

· 2.1 Classification of the substance or mixture

· Classification according to Regulation (EC) No 1272/2008

Skin Irrit. 2 H315 Causes skin irritation.

Eye Dam. 1 H318 Causes serious eye damage.

STOT SE 3 H335 May cause respiratory irritation.

### · 2.2 Label elements

· Labelling according to

**Regulation (EC) No 1272/2008** The product is classified and labelled according to the GB CLP regulation.

Hazard pictograms



Danger

· Signal word

(Contd. on page 2)



## Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023

Version number 23 (replaces version 22)

Revision: 12.08.2023

Page 2/8

Trade name MC-RIM PROTECT

		(Control of page )
		(Contd. of page
· Hazard-determining		
components of labelling:	Portland cemen	nt
	Flue dust, portla	and cement
· Hazard statements	H315 Causes s	kin irritation.
	H318 Causes s	erious eye damage.
	H335 May caus	se respiratory irritation.
· Precautionary statements	P261	Avoid breathing dust/fume/gas/mist/vapour.
-		spray.
	P305+P351+P3	338 IF IN EYES: Rinse cautiously with water fo
		several minutes. Remove contact lenses,
		present and easy to do. Continue rinsing.
	P310	Immediately call a POISON CENTER/doctor.
	P321	Specific treatment (see on this label).
	P362+P364	Take off contaminated clothing and wash
		before reuse.
	P403+P233	Store in a well-ventilated place. Keep contained
		tightly closed.
· 2.3 Other hazards		
· Results of PBT and vPvB as	sessment	
· PBT:	Not applicable.	
· vPvB:	Not applicable.	

## SECTION 3: Composition/information on ingredients

· 3.2 Mixtures	
----------------	--

<ul> <li>Description:</li> </ul>	Mixture consisting of the following components.	
· Dangerous compo	nents:	
	Portland cement	<i>≥</i> 20- <i>≤</i> 30%
EINECS: 266-043-4	Eye Dam. 1, H318; Skin Irrit. 2, H315; STOT SE 3, H335	
CAS: 68475-76-3	Flue dust, portland cement	≥1-<1.5%
	Eye Dam. 1, H318; Skin Irrit. 2, H315; STOT SE 3, H335	
· Additional informat	tion For the wording of the listed hazard phrases refer to se	ection 16.

4.1 Description of first a		
After inhalation	Supply fresh air.	
After skin contact	Instantly wash with water and soap and rinse thoroughly	Ι.
After eye contact	Rinse opened eye for several minutes under running was Seek medical treatment.	nter.
After swallowing	Rinse out mouth and then drink plenty of water. Seek medical treatment.	
4.2 Most important sympand effects, both acute a		
delayed	No further relevant information available.	
-	(Cor	itd. on page

GB



Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023

Version number 23 (replaces version 22)

Revision: 12.08.2023

(Contd. of page 2)

Page 3/8

#### Trade name MC-RIM PROTECT

• 4.3 Indication of any immediate medical attention

and special treatment needed No further relevant information available.

### **SECTION 5: Firefighting measures**

- · 5.1 Extinguishing media
- · Suitable extinguishing agents Use fire fighting measures that suit the environment.
- 5.2 Special hazards arising from the substance or mixture
- 5.3 Advice for firefighters
   Protective equipment:
- No special measures required.

No further relevant information available.

### SECTION 6: Accidental release measures

 6.1 Personal precautions, protective equipment and emergency procedures
 6.2 Environmental

Not required.

No special measures required.

6.3 Methods and material for containment and cleaning up: Collect mechanically.

 6.4 Reference to other sections

precautions:

See Section 7 for information on safe handling See Section 8 for information on personal protection equipment. See Section 13 for information on disposal.

### **SECTION 7: Handling and storage**

 7.1 Precautions for safe handling
 Prevent formation of dust.
 Information about protection against explosions and fires: No special measures required.

· 7.2 Conditions for safe storage, including any incompatibilities

13

· Storage

- Requirements to be met by storerooms and containers: No special requirements.
   Information about storage in one common storage facility: Not required.
   Further information about storage conditions: Keep container tightly sealed.
- Storage class

(Contd. on page 4)

GB



Page 4/8

# Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023

Version number 23 (replaces version 22)

Revision: 12.08.2023

(Contd. of page 3)

Trade name MC-RIM PROTECT

• 7.3 Specific end use(s) No further relevant information available.

Components with critical values that require monitoring at the workplace:         65997-15-1 Portland cement         WEL       Long-term value: 10* 4** mg/m³         'inhalable dust **respirable dust         DNELs         65997-15-1 Portland cement         Inhalative       DNEL 1 mg/m³ (ArL)         Additional information:       The lists that were valid during the compilation were used as basi         8.2 Exposure controls       Appropriate engineering         controls       No further data; see section 7.         Individual protection measures, such as personal protective equipment         General protective and         hygienic measures       Keep away from foodstuffs, beverages and food.         Instantly remove any soiled and impregnated garments.         Wash hands during breaks and at the end of the work.         Avoid contact with the eyes and skin.         Breathing equipment:       In case of brief exposure or low pollution or when application         performed at confined area with adequate mechanical ventilatii meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing apparatus. In case of intensive or longer exposure use breathing apparatus that is independent of circulating air.         Hand protection       After use of gloves apply skin-cleaning agents and skin cosmetics.         Material of gloves       Selection of the suitable gloves d	8.1 Control parameters	
65997-15-1 Portland cement         WEL       Long-term value: 10* 4** mg/m³         'inhalable dust **respirable dust         DNELs         65997-15-1 Portland cement         Inhalative       DNEL 1 mg/m³ (ArL)         Additional information:       The lists that were valid during the compilation were used as basi         8.2 Exposure controls       No further data; see section 7.         Appropriate engineering       No further data; see section 7.         Individual protection measures, such as personal protective equipment         General protective and       Keep away from foodstuffs, beverages and food.         Instantly remove any solled and impregnated garments.         Wash hands during breaks and at the end of the work.         Avoid contact with the eyes and skin.         Breathing equipment:       In case of brief exposure or low pollution or when application         performed at confined area with adequate mechanical ventilatii meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing the apparatus that is independent of circulating air.         Hand protection       Selection of the gloves material on consideration of the penetratic times, rates of diffusion and the degradation         After use of gloves.       Selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparati	•	values that require monitoring at the workplace:
*inhalable dust **respirable dust         DNELs         65997-15-1 Portland cement         Inhalative DNEL 1 mg/m³ (ArL)         Additional information:         8.2 Exposure controls         Appropriate engineering controls         No further data; see section 7.         Individual protection measures, such as personal protective equipment         General protective and hygienic measures         Keep away from foodstuffs, beverages and food. Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.         Breathing equipment:       In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilatio meeting local authority requirements, use breathing apparatus. In case of intensive or longer exposure use breathing apparatus. In case of diffusion and the degradation After use of gloves.         Material of gloves       Nitrile rubber, NBR Butyl rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on th material, but also on further marks of quality and varies fro manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to ta application.         Peneteration time of glove material       The exact break trough time has to be observed. Safety glasses.	-	
*inhalable dust **respirable dust         DNELs         65997-15-1 Portland cement         Inhalative DNEL 1 mg/m³ (ArL)         Additional information:         8.2 Exposure controls         Appropriate engineering controls         No further data; see section 7.         Individual protection measures, such as personal protective equipment         General protective and hygienic measures         Keep away from foodstuffs, beverages and food. Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.         Breathing equipment:       In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilatio meeting local authority requirements, use breathing apparatus. In case of intensive or longer exposure use breathing apparatus. In case of diffusion and the degradation After use of gloves.         Material of gloves       Nitrile rubber, NBR Butyl rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on th material, but also on further marks of quality and varies fro manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to ta application.         Peneteration time of glove material       The exact break trough time has to be observed. Safety glasses.	WEL Long-term value: 10* 4	4** mq/m³
65997-15-1 Portland cement         Inhalative       DNEL       1 mg/m³ (ArL)         Additional information:       The lists that were valid during the compilation were used as basi         8.2 Exposure controls       Appropriate engineering controls         Appropriate engineering       No further data; see section 7.         Individual protection measures, such as personal protective equipment         General protective and         hygienic measures       Keep away from foodstuffs, beverages and food.         Instantly remove any solled and impregnated garments.         Wash hands during breaks and at the end of the work.         Avoid contact with the eyes and skin.         Breathing equipment:       In case of brief exposure or low pollution or when application         performed at confined area with adequate mechanical ventilation meeting local authority requirements, use breathing apparatus that is independent of circulating air.         Hand protection       Protective gloves.         Selection of the glove material on consideration of the penetratio times, rates of diffusion and the degradation         After use of gloves       Nitrile rubber, NBR         Butyl rubber, BR       The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation ne several substances, the resistance of the glove material can not lo calculated in advance and has therefore to		
Inhalative       DNEL       1 mg/m³ (ArL)         Additional information:       The lists that were valid during the compilation were used as basi         8.2 Exposure controls       No further data; see section 7.         Individual protection measures, such as personal protective equipment         General protective and         hygienic measures       Keep away from foodstuffs, beverages and food.         Instantly remove any solied and impregnated garments.         Wash hands during breaks and at the end of the work.         Avoid contact with the eyes and askin.         Breathing equipment:       In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilation meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing apparatus that is independent of circulating air.         Hand protection       Protective gloves.         Selection of the glove material on consideration of the penetratit times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics.         Material of gloves       Nitrile rubber, NBR         Butyl rubber, BR       The selection of the suitable gloves does not only depend on tim material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not in calculated in advance and has therefore to be checked prior to tin aplication.         <	DNELs	
Additional information:       The lists that were valid during the compilation were used as basi         8.2 Exposure controls       Appropriate engineering         Appropriate engineering       No further data; see section 7.         Individual protection measures, such as personal protective equipment       General protective and         hygienic measures       Keep away from foodstuffs, beverages and food.         Instantly remove any soiled and impregnated garments.       Wash hands during breaks and at the end of the work.         Avoid contact with the eyes and skin.       No forther exposure or low pollution or when application performed at confined area with adequate mechanical ventilatic meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathin apparatus. In case of diffusion and the degradation         Hand protection       Protective gloves.         Selection of the glove material on consideration of the penetratic times, rates of diffusion and the degradation         After use of gloves       Nitrile rubber, NBR         Butyl rubber, BR       The selection of the suitable gloves does not only depend on timaterial, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not application.         Penetration time of glove       The exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.         Safety glasses       Tightly s	65997-15-1 Portland cemei	nt
Additional information:       The lists that were valid during the compilation were used as basi         8.2 Exposure controls       Appropriate engineering         Appropriate engineering       No further data; see section 7.         Individual protection measures, such as personal protective equipment       General protective and         hygienic measures       Keep away from foodstuffs, beverages and food.         Instantly remove any soiled and impregnated garments.       Wash hands during breaks and at the end of the work.         Avoid contact with the eyes and skin.       No forther exposure or low pollution or when application performed at confined area with adequate mechanical ventilatic meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathin apparatus. In case of diffusion and the degradation         Hand protection       Protective gloves.         Selection of the glove material on consideration of the penetratic times, rates of diffusion and the degradation         After use of gloves       Nitrile rubber, NBR         Butyl rubber, BR       The selection of the suitable gloves does not only depend on timaterial, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not application.         Penetration time of glove       The exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.         Safety glasses       Tightly s	Inhalative DNEL 1 mg/m <sup>3</sup> ()	ArL)
Appropriate engineering controlsNo further data; see section 7.Individual protection measures, such as personal protective equipmentGeneral protective and hygienic measuresKeep away from foodstuffs, beverages and food. Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilati meeting local authority requirements, use breathing filt apparatus that is independent of circulating air.Hand protectionProtective gloves. Selection of the glove material on consideration of the penetrati times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmeticsMaterial of glovesNitrile rubber, NBR Butyl rubber, BRPenetration time of glove material, but also on further marks of quality and varies fro manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not i calculated in advance and has therefore to be checked prior to t application.Penetration time of glove materialThe exact break trough time has to be found out by th manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.	Additional information:	
Appropriate engineering controlsNo further data; see section 7.Individual protection measures, such as personal protective equipmentGeneral protective and hygienic measuresKeep away from foodstuffs, beverages and food. Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilati meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing apparatus that is independent of circulating air.Hand protectionProtective gloves. Selection of the glove material on consideration of the penetratic times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmeticsMaterial of glovesNitrile rubber, NBR Butyl rubber, BRPenetration time of glove material, but also on further marks of quality and varies fro manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not I calculated in advance and has therefore to be checked prior to ti application.Penetration time of glove materialThe exact break trough time has to be found out by th manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.	8 2 Exposure controls	
controlsNo further data; see section 7.Individual protection measures, such as personal protective equipmentGeneral protective andhygienic measuresKeep away from foodstuffs, beverages and food. Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilati meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing apparatus. In case of intensive or longer exposure use breathing apparatus. In case of intensive or longer exposure use breathing apparatus. In case of intensive or longer exposure use breathing apparatus. In case of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not I calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
Individual protection measures, such as personal protective equipmentGeneral protective and hygienic measuresKeep away from foodstuffs, beverages and food. Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilati meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathin apparatus. In case of office gloves. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics. Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on to material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to to application.Penetration time of glove materialThe exact break trough time has to be found out by ti manufacturer of the protective gloves and has to be observed. Safety glasses. Tightly sealed safety glasses.		No further data; see section 7.
hygienic measuresKeep away from foodstuffs, beverages and food. Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilati meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathin apparatus that is independent of circulating air.Hand protectionProtective gloves. Selection of the glove material on consideration of the penetrati times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on to material, but also on further marks of quality and varies fro manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not i calculated in advance and has therefore to be checked prior to t application.Penetration time of glove materialThe exact break trough time has to be found out by th manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.	Individual protection meas	
Instantly remove any soiled and impregnated garments. Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin. In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilatin meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing Hand protection Hand protection Material of gloves Material of gloves Material of gloves Penetration time of glove material Eye/face protection In case of break trough time has to be found out by th manufacturer of the protective gloses and has to be observed. Safety glasses Tightly sealed safety glasses.	General protective and	
Wash hands during breaks and at the end of the work. Avoid contact with the eyes and skin.Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilati imeeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing apparatus that is independent of circulating air.Hand protectionProtective gloves. Selection of the glove material on consideration of the penetrati times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics.Material of glovesNBR Butyl rubber, BR The selection of the suitable gloves does not only depend on to material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not in calculated in advance and has therefore to be checked prior to tri application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.	hygienic measures	
Avoid contact with the eyes and skin.Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilati meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathin apparatus that is independent of circulating air.Hand protectionProtective gloves. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not in calculated in advance and has therefore to be checked prior to tri application.Penetration time of glove materialThe exact break trough time has to be found out by th manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
Breathing equipment:In case of brief exposure or low pollution or when application performed at confined area with adequate mechanical ventilation meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing apparatus that is independent of circulating air.Hand protectionProtective gloves. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics.Material of glovesNitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on to material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to to application.Penetration time of glove materialThe exact break trough time has to be found out by th manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
Hand protectionperformed at confined area with adequate mechanical ventilation meeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathing apparatus that is independent of circulating air. Protective gloves. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.	Breathing equipment:	
Hand protectionmeeting local authority requirements, use breathing filt apparatus. In case of intensive or longer exposure use breathin apparatus that is independent of circulating air. Protective gloves. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not be calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.	Dieatinig equipment.	
Hand protectionapparatus. In case of intensive or longer exposure use breathin apparatus that is independent of circulating air. Protective gloves. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not it calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
Hand protectionProtective gloves. Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not if calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		apparatus. In case of intensive or longer exposure use breathin
Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies fro manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not if calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
Material of glovestimes, rates of diffusion and the degradation After use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.Eye/face protectionSafety glasses Tightly sealed safety glasses.	Hand protection	
Material of glovesAfter use of gloves apply skin-cleaning agents and skin cosmetics Nitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not be calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
Material of glovesNitrile rubber, NBR Butyl rubber, BR The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
Butyl rubber, BRThe selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.	Material of gloves	
The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to the application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed. Safety glasses Tightly sealed safety glasses.		
material, but also on further marks of quality and varies from manufacturer to manufacturer. As the product is a preparation several substances, the resistance of the glove material can not calculated in advance and has therefore to be checked prior to to application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.Eye/face protectionSafety glasses Tightly sealed safety glasses.		The selection of the suitable gloves does not only depend on t
several substances, the resistance of the glove material can not a calculated in advance and has therefore to be checked prior to to application.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.Eye/face protectionSafety glasses Tightly sealed safety glasses.		material, but also on further marks of quality and varies fro
calculated in advance and has therefore to be checked prior to t application.Penetration time of glove materialThe exact break trough time has to be found out by to manufacturer of the protective gloves and has to be observed.Eye/face protectionSafety glasses Tightly sealed safety glasses.		
Penetration time of glove materialapplication.Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.Eye/face protectionSafety glasses Tightly sealed safety glasses.		
Penetration time of glove materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.Eye/face protectionSafety glasses Tightly sealed safety glasses.		
materialThe exact break trough time has to be found out by the manufacturer of the protective gloves and has to be observed.Eye/face protectionSafety glasses Tightly sealed safety glasses.	Penetration time of alove	αμμιταίιοπ.
Eye/face protectionmanufacturer of the protective gloves and has to be observed.Safety glassesSafety glasses.		The exact break trough time has to be found out by th
Eye/face protection         Safety glasses           Tightly sealed safety glasses.		
	Eye/face protection	Safety glasses

- GB



Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023

Version number 23 (replaces version 22)

Revision: 12.08.2023

Trade name MC-RIM PROTECT

· Body protection:

Protective work clothing.

(Contd. of page 4)

Page 5/8

9.1 Information on basic physical and chei	mical properties
General Information	
Colour:	Grey
Smell:	Odourless
Melting point/freezing point:	Not determined
Boiling point or initial boiling point and	
boiling range	2230 °C (14808-60-7 Quartz (SiO2))
Flash point:	Not applicable
рН	Not applicable.
, Viscosity:	
Kinematic viscosity	Not applicable.
dynamic:	Not applicable.
Solubility	- F F
Water:	Unsoluble
Steam pressure at 1732 °C:	13.5 hPa (14808-60-7 Quartz (SiO2))
Density and/or relative density	
Density	Not determined
•	
9.2 Other information	
Appearance:	Dowdor
Form:	Powder
Important information on protection of hea	
and environment, and on safety.	Draduct is not colficerting
Self-inflammability:	Product is not selfigniting.
Explosive properties:	Product is not explosive.
Information with regard to physical haz	ard
classes	
Explosives	Void
Flammable gases	Void
Aerosols	Void
Oxidising gases	Void
Gases under pressure	Void
Flammable liquids	Void
Flammable solids	Void
Self-reactive substances and mixtures	Void
Pyrophoric liquids	Void
Pyrophoric solids	Void
Self-heating substances and mixtures	Void
Substances and mixtures, which emit	
flammable gases in contact with water	Void
Oxidising liquids	Void
Oxidising solids	Void
Organic peroxides	Void



Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023

Version number 23 (replaces version 22)

Revision: 12.08.2023

(Contd. of page 5)

Trade name MC-RIM PROTECT

· Corrosive to metals · Desensitised explosives

Void Void

### SECTION 10: Stability and reactivity

· 10.1 Reactivity

10.2 Chemical stability
 Thermal decomposition /

No further relevant information available.

No decomposition if used according to specifications.

conditions to be avoided: • 10.3 Possibility of hazardous reactions • 10.4 Conditions to avoid • 10.5 Incompatible materials:

No further relevant information available.

No dangerous reactions known

- : No further relevant information available.
- 10.6 Hazardous decomposition products: No dangerous decomposition products known

### **SECTION 11: Toxicological information**

• 11.1 Information on hazard classes as defined in Regulation (EC) No 1272/2008

- Acute toxicity Based on available data, the classification criteria are not met.
- · LD/LC50 values that are relevant for classification: 65997-15-1 Portland cement Dermal LD50 2000 mg/kg (rabbit) Inhalative LC50/4 h 5 mg/l (rat) · Skin corrosion/irritation Causes skin irritation. · Serious eye damage/irritation Causes serious eye damage. Based on available data, the classification criteria are not met. · Germ cell mutagenicity Based on available data, the classification criteria are not met. · Carcinogenicity · Reproductive toxicity Based on available data, the classification criteria are not met. • STOT-single exposure May cause respiratory irritation. · STOT-repeated exposure Based on available data, the classification criteria are not met. · Aspiration hazard Based on available data, the classification criteria are not met. 11.2 Information on other hazards · Endocrine disrupting properties 128-37-0 2,6-Di-tert-butyl-p-cresol List II
  - SECTION 12: Ecological information

     12.1 Toxicity

     Aquatic toxicity:
     No further relevant information available.

     12.2 Persistence and degradability
     No further relevant information available.

     12.3 Bioaccumulative potential
     No further relevant information available.

Page 6/8



Page 7/8

## Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023

Version number 23 (replaces version 22)

Revision: 12.08.2023

### Trade name MC-RIM PROTECT

· 12.4 Mobility in soil	(Contd. of page 6) No further relevant information available.
· 12.5 Results of PBT and vF	PvB assessment
· PBT:	Not applicable.
· vPvB:	Not applicable.
<ul> <li>12.6 Endocrine disrupting</li> </ul>	
properties	For information on endocrine disrupting properties see section 11.
12.7 Other adverse effects	
· Additional ecological infor	mation:
· General notes:	Do not allow undiluted product or large quantities of it to reach ground water, water bodies or sewage system.

## **SECTION 13: Disposal considerations**

<ul> <li>13.1 Waste treatment methods</li> <li>Recommendation</li> </ul>	ods Must not be disposed of together with household garbage. Do not allow product to reach sewage system.
<ul> <li>Uncleaned packagings:</li> <li>Recommendation:</li> </ul>	Empty contaminated packagings thoroughly. They can be recycled after thorough and proper cleaning.

### **SECTION 14: Transport information**

<ul> <li>14.1 UN number or ID number</li> <li>ADR, ADN, IMDG, IATA</li> </ul>	Void	
<ul> <li>14.2 UN proper shipping name</li> <li>ADR, ADN, IMDG, IATA</li> </ul>	Void	
· 14.3 Transport hazard class(es)		
· ADR, ADN, IMDG, IATA · Class	Void	
· 14.4 Packing group · ADR, IMDG, IATA	Void	
· 14.5 Environmental hazards: · Marine pollutant:	No	
<sup>•</sup> 14.6 Special precautions for user	Not applicable.	
<ul> <li>14.7 Maritime transport in bulk accord IMO instruments</li> </ul>	ing to Not applicable.	
· UN "Model Regulation":	Void	

### SECTION 15: Regulatory information

 15.1 Safety, health and environmental regulations/



Page 8/8

## Safety data sheet according to 1907/2006/EC, Article 31

Printing date 12.08.2023 Version number 23 (replaces version 22) Revision: 12.08.2023 Trade name MC-RIM PROTECT (Contd. of page 7) · legislation specific for the substance or mixture No further relevant information available. · 15.2 Chemical safety assessment: A Chemical Safety Assessment has not been carried out. **SECTION 16: Other information** These data are based on our present knowledge. However, they shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship. · Relevant phrases H315 Causes skin irritation. H318 Causes serious eye damage. H335 May cause respiratory irritation. · Department issuing data specification sheet: Environment protection department. · Abbreviations and acronyms: RID: Règlement international concernant le transport des marchandises dangereuses par chemin de fer (Regulations Concerning the International Transport of Dangerous Goods by Rail) ICAO: International Civil Aviation Organisation ADR: Accord relatif au transport international des marchandises dangereuses par route (European Agreement Concerning the International Carriage of Dangerous Goods by Road) IMDG: International Maritime Code for Dangerous Goods IATA: International Air Transport Association GHS: Globally Harmonised System of Classification and Labelling of Chemicals EINECS: European Inventory of Existing Commercial Chemical Substances ELINCS: European List of Notified Chemical Substances CAS: Chemical Abstracts Service (division of the American Chemical Society) DNEL: Derived No-Effect Level (UK REACH) LC50: Lethal concentration, 50 percent LD50: Lethal dose, 50 percent PBT: Persistent, Bioaccumulative and Toxic vPvB: very Persistent and very Bioaccumulative Skin Irrit. 2: Skin corrosion/irritation - Category 2 Eye Dam. 1: Serious eye damage/eye irritation - Category 1 STOT SE 3: Specific target organ toxicity (single exposure) – Category 3 • \* Data compared to the previous version altered.